## State of New Mexico

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR 1 1 2013

	Oil Co	onservation Division	Hobbs Distri	ct Office		DE/	^EII /EF\	
BRADENHEAD TEST REPORT						RECEIVED		
Operator Name  Operator Name					*API Number			
Corloco Phillips Property Name  SEMU PERMINAY					300 250 624 200 Well No.			
					25			
		7. Surface Loca		<del></del>				
UL-Lot Section	Township Range 376	Feet from	N/S Line Feet			E/W Line	County	
11 33	205 378	Well State		660	<u> </u>	pec c	1 1/21.	
Well Status	SHUT-IN	PRODUCIN	ING DA		13			
OPEN	RDADENUEAD AND IN	FERMEDIATE TO ATMOSPI	TERE INDIVIDUA			S RA CH		
		OBSERVED D		DET FOR 15 1	, IIII (C LEA	DACH		
If bradenhead flowed water								
	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod		(D)Prod-Tubing		(E)Tubing	
Pressure	x	<u> </u>	>	<	0		1200 PB	
Flow Characteristics							_	
Puff	Y / 🗷	Y / N	Y /	1.	Y/00			
Stendy Flow	Y/100	Y/N	Y /		Y / 60			
Surges  Down to nothing	Y / 809 Y / 809	Y/N Y/N	Y / Y /		Y / 🚳		_	
Gas or Oil	Y/20	Y / N	1		Y/69		_	
Water	Y/(N)	Y/N	Y/N Y/N		Y / (C)		4	
							J	
If bradenhead flowed water	, check all of the descripti	ons that apply:					•	
CLEAR	FRESH	SALTY	SULFUR			BLACK	•	
Remarks:			·- // // // // // // // // // // // // //			•	-	
	·							
	*		•					
			4.					
			•	•				
						•		
	·	***************************************	·					
			•					
Signature:				OIL CONSERVATION DIVISION				
Printed-name: Sign 1889				Entered into RBDMS				
Title: 1880				Re-test				
E-mail Address: 500	M. herrer	D Carera Hirthy	25 Com			•		

MARCH 11

FOR RECORD ONLY

2013

Phone: Witness: