

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAR 26 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	API Number 30 025 02399
Property Name MESCALERO RIDGE UNIT	Well No. 282

7. Surface Location

UL Lot B	Section 28	Township 19S	Range 34E	Feet from 660	N/S Line N	Feet from 1980	E/W Line E	County Lea
--------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING ☒	DATE 3/11/13
-------------	---------	--	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	0	500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

- Puff of oil & water from casing
- Down to nothing ✓

Signature: [Signature]	ELG/OCD 3-26-2013
Printed name: JUNIOR CONTRERAS	OIL CONSERVATION DIVISION
Title: PRODUCTION SPECIALIST	Entered into RBDMS
E-mail Address: econtreras@linnenergy.com	Re-test
Date: 3/11/13	Phone: 575/909-0081
Witness:	

MAR 28 2013