

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corporation	API Number 30-025- 05773
Property Name NMGSAU	Well No. 1503

2. Surface Location

UL - Lot	Section 31	Township 19S	Range 37 E	Feet from	N/S Line	Feet From	E/W Line	County Lea
----------	---------------	-----------------	---------------	-----------	----------	-----------	----------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING (inj)	DATE 3-18-13
-------------	---------	--------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm Casing	(D)Prod Casing	(E)Tubing
Pressure	0		0	450	495
Flow Characteristics					
Puff	Y / N	Y / N	(Y) / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(D) Continuous flow on casing. Shut in tubing and flow stopped. Opened tubing and flow started. Shut in well until the problem can be repaired.

FAILURE

Signature: 	ELG/ocd 4-1-2013
Printed name: Jim Ellison	OIL CONSERVATION DIVISION
Title: Instrument Technician	Entered into RBDMS
E-mail Address: JD.Ellison@apachecorp.com	Re-test
Date: 3-18-13	
Phone: 575-441-7734	
Witness:	

APR 08 2013