| Submit 1 Copy To Appropriate District Office | State of New M | exico | Form C-103 | | | |
|--|---|----------------------------------|---|-------------------------|--|--|
| District I – (575) 393-6161 | Energy, Minerals and Nat | ural Resources | | evised August 1, 2011 | | |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | | | WELL API NO. 30-025-31265 | | | |
| 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION | | 5. Indicate Type of Lea | ıse | | |
| <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | 1220 South St. Fra | | STATE 🖂 | FEE 🗌 🖊 | | |
| <u>District IV</u> – (505) 476-3460 | Santa Fe, NM 8 | 37505 | 6. State Oil & Gas Leas | se No. | | |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | | | | |
| | CES AND REPORTS ON WELL | S | 7. Lease Name or Unit | Agreement Name | | |
| (DO NOT USE THIS FORM FOR PROPO | | | | | | |
| DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) | SATION FOR PERMIT (FORM C-101) F | OK SOCH | WEST LOVINGTON | UNIT | | |
| 1. Type of Well: Oil Well 🛛 | Gas Well Other Water Inject | tion | 8. Well Number: 81 | | | |
| 2. Name of Operator | - 11000 | | 9. OGRID Number: 24 | 1333 | | |
| Chevron Midcontinent, L.P. 3. Address of Operator | ADD 1 | 2 2013 | 10. Pool name or Wild | cat / | | |
| 15 Smith Road Midland, TX 79705 | AFN * | D FAIA | Lovington, Upper San | / | | |
| 4. Well Location | | | | | | |
| | 105'feet from theNorth | EIVED |)5' feet from the | WEST line | | |
| Section 9 | Township 17-S | Range 36-E | NMPM | County Lea | | |
| Section | 11. Elevation (Show whether DI | | | | | |
| | 3879' GL | , 1111 <i>D</i> , 111, 011, 010. | | | | |
| 12. Check A | Appropriate Box to Indicate N | Nature of Notice, | Report or Other Data | | | |
| NOTICE OF IN | STENTION TO | CLID | CECUENT DEDOD | T 05 | | |
| PERFORM REMEDIAL WORK | ITENTION TO: PLUG AND ABANDON ⊠ | REMEDIAL WOR | SEQUENT REPOR | (TOF: ERING CASING □ | | |
| TEMPORARILY ABANDON | CHANGE PLANS | COMMENCE DRI | - | | | |
| PULL OR ALTER CASING | MULTIPLE COMPL | CASING/CEMEN | | | | |
| DOWNHOLE COMMINGLE | | | | | | |
| • | _ | | | | | |
| OTHER: | | OTHER: | 1 - 1 1 - 1 - 1 - 1 - 1 - 1 | | | |
| | leted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA | | | | | |
| proposed completion or rec | | ic. To Multiple Col | inpletions. Attach welloo. | re diagram or | | |
| | TD-5230' PB-4640' Perfs - 4727 | ' – 4780', 4920' – 50 |)25', 5060' – 5146' | | | |
| | 8-5/8 " 24# csg @ 365' w/300 sks | | | | | |
| ; | 5-1/2" 15.5# csg @ 5230' w/1950 |) sks, , TOC – SURI | FACE, Circulated | | | |
| 1. MIRUWSU. NDWH. NU | B∩P | | • | | | |
| 2. Tag CIBP @ 4640' w/25 s | | | | | | |
| 3. TIH tubing. Circulate well | l with 9.5 PPG plugging mud. Pres | | | indings | | |
| | s C cement @ 3350' – 3150', CTC | | | • | | |
| | s C cement @ 2050' – 1800', CTC cs of Class C cement @ 465' – Su | | Top of Salt) | | | |
| | ors 3' below grade. Weld on dry h | | cation | | | |
| | grader word on any in | | | | | |
| | | | | | | |
| | | | | bo notified | | |
| Spud Date: | Rig Release D | The Oil Cons | servation Division Must or to the beginning of p | lugging operations. | | |
| | | 24 hours pric | or to the beginning of P | | | |
| | | | | | | |
| I hereby certify that the information | above is true and complete to the b | est of my knowledg | e and belief. | | | |
| SIGNATURE / W | TITLE | Representative | DATE | 04/12/2013 | | |
| SIGNATURE | / · · · · · · · · · · · · · · · · · · · | Kepresentative | DATE | 04/12/2013 | | |
| Type or print name <u>Robert Hol</u> | den E-mail address | s: <u>rholden@keye</u> ne | ergy.com PHONE: 432 | -523-5155 | | |
| For State Use Only | | | 7 0 | | | |
| APPROVED BY: Mark Whitelen TITLE Compliance Officer DATE 04-12-2013 | | | | | | |
| APPROVED BY: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | TILE WI | mpriance C | DATE C | 1-12-4013 | | |
| conditions of ripproval (if miy). | O'A- | • | | | | |
| | ۲Λ. | | | - nn13 | | |

APR 1.5 2013

Well: West Lovington Unit 81

Field:Lovington

Reservoir: San Andres

Location:

105' FNL & 1305' FWL Section: 9 (NW/4 NW/4)

Township: 17S Range: 36E Unit: D County: Lea State: NM

Elevations: GL: 3879 KB: 3895 DF: 3894

| Log Formation Tops | | | | | |
|--------------------|------|--|--|--|--|
| Seven Rivers | 3348 | | | | |
| Queen | 3770 | | | | |
| Grayburg | 4459 | | | | |
| San Andres | 4677 | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

TUBING DETAIL - 11/30/2007 CIBP @ 4640


This wellbore diagram is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office wellfiles and computer databases as of the update below. Verify what is in the hole with the wellfile in the Lovington Field Office. Discuss w/WEO Engineer, WO Rep, OS, ALS, & FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.

CIBP @ 4640

Prod. Csg: 5 1/2" 15.5# Set: 5230 w/1950 sx cmt Hole Size: 7 7/8" Circ: Yes TOC: surface TOC By: circulation

Updated: 3/4/2013 by WPJ

Current Wellbore Diagram



Well ID Info:

Chevno: OP9877 API No: 30-025-31265 L5/L6: FA3 / 0900 Spud Date: 7/30/91 TD Reached: 8/8/9 Compl. Date: 10/9/12

Surface Csg: 8 5/8" 24# Set: @ 365' w/300 sx cmt Hole Size: 12 1/4" Circ: yes TOC: surface TOC By: circulation

Initial Completion:

10/9/1991 - (San Andres) Perf 4727-37, 4752-55, 4773-80, 4877-81, 4940-43. 4988-90, 4994-5004, 5012-19, 5025-28, 5074-77, 5108-14, 5134-42, 5144-46;

A/7000 gals 20% SGA acid & 25 tons CO2

Subsequent Work

11/19/1993 - Reduce water production set CIBP @ 5060 - RTP

6/22/1994 - Reduce water production set CIBP @ 4920 - RTP

11/30/2007 - TA set CIBP @ 4640 - MIT @ 500 psi for 30 min

Perfs

4727-37, 4752-55, 4773-80, 4877-81,

Status

San Andres - CIBP CIBP @ 4920 4940-43, 4988-90, 4994-5004, 5012-19, 5025-2 San Andres - CIBP

CIBP @ 5060 5074-77, 5108-14, 5134-42, 5144-46

San Andres - CIBP

TD: 5230 COTD: 5161 PBTD: 4640

Well: West Lovington Unit 81



Reservoir: San Andres

Location:

105' FNL & 1305' FWL Section: 9 (NW/4 NW/4)

Township: 17S Range: 36E Unit: D County: Lea State: NM

Elevations:

GL: 3879 KB: 3895 DF: 3894

| Log Formation Tops | 5 |
|--------------------|------|
| Seven Rivers | 3348 |
| Queen | 3770 |
| Grayburg | 4459 |
| San Andres | 4677 |
| | |
| | |
| | |
| | |
| | |
| | 1 |


TUBING DETAIL - 11/30/2007 CIBP @ 4640

This wellbore diagram is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office wellfiles and computer databases as of the update below. Verify what is in the hole with the wellfile in the Lovington Field Office. Discuss w/WEO Engineer, WO Rep, OS, ALS, & FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.

CIBP @ 4640

Prod. Csg: 5 1/2" 15.5# Set: 5230 w/1950 sx cmt Hole Size: 7 7/8" Circ: Yes TOC: surface TOC By: circulation

Current Wellbore Diagram



Well ID Info:

Chevno: OP9877 API No: 30-025-31265 L5/L6: FA3 / 0900 Spud Date: 7/30/91 TD Reached: 8/8/9 Compl. Date: 10/9/12

Surface Csg: 8 5/8" 24# Set: @ 365' w/300 sx cmt Hole Size: 12 1/4" Circ: yes TOC: surface TOC By: circulation

Initial Completion:

10/9/1991 - (San Andres) Perf 4727-37, 4752-55, 4773-80, 4877-81, 4940-43. 4988-90, 4994-5004, 5012-19, 5025-28, 5074-77, 5108-14, 5134-42, 5144-46;

A/7000 gals 20% SGA acid & 25 tons CO2

Subsequent Work

11/19/1993 - Reduce water production set CIBP @ 5060 - RTP 6/22/1994 - Reduce water production set CIBP @ 4920 - RTP

11/30/2007 - TA set CIBP @ 4640 - MIT @ 500 psi for 30 min

TOP OF SALT

1850

BOTTOM OF SALT

Set Pluy W/25 sks @ 3350-3150, 1706, Woi +7A6 (BOTTOM SALT)

THE CIBPE 4640 Was sks of cmi

4727-37, 4752-55, 4773-80, 4877-81,

CIBP @ 4920 4940-43, 4988-90, 4994-5004, 5012-19, 5025-2 San Andres - CIBP

San Andres - CIBP

CIBP @ 5060 5074-77, 5108-14, 5134-42, 5144-46

San Andres - CIBP

TD: 5230 COTD: 5161 PBTD: 4640

| Wellname: | WL | .U # 81 | Permit #: | | Rig Mobe Date: Rig Demobe Date: | | | | | |
|-----------------|------|---------|--|--|------------------------------------|---|--------------|--|--|----------|
| County: | Le | Lea Co. | | | | | | | | |
| Inspection Date | Time | By Whom | Any drips or leaks from steel tanks, lines or punot contained? * Explain | | or pumps | Has any hazardous waste been disposed of in system? | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | <u> </u> | | | |
| | | | | | | | <u> </u> | | | |
| | | | | | | | | | | |
| | | | | | | | - | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | - | | | | | |
| | | | | | , | <u> </u> | | | | |
| | | | | | | | | <u> </u> | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | ļ · | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | ļ | - | | <u> </u> |
| | | | | | | | | | | |

All circulating systems to be inspected DAILY during drilling operations.

*Any leak of the steel tanks, lines or pumps shall be reported to the NMOCD and repaired within 48 hours.

WLU #81

C-144 CLEZ P&A Rig Lay out

RIG

Well Head

0

