

MAR 27 2013

District 1

1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corporation	API Number 30-025-12471
Property Name NMGSAU	Well No. 1411

2. Surface Location

UL - Lot K	Section 36	Township 19S	Range 36E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING (inj)	DATE
-------------	---------	--------------------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm Csng	(D) Prod Csng	(E) Tubing
Pressure			120	300	725
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(C) Bled gas to 0 psi in 5 seconds
 (D) Bled water to 0 psi in 45 seconds

Signature: 	Oil Conservation Division
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Technician	Re-test
E-mail Address: JD.Ellison@apachecorp.com	
Date: 3-21-13	Phone: 575-441-7734
Witness:	

APR 15 2013