

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                        |                            |
|----------------------------------------|----------------------------|
| Operator Name<br>XTO Energy, Inc       | API Number<br>30-025-21751 |
| Property Name<br>North Vacuum ABO Unit | Well No.<br>112            |

7. Surface Location

|               |               |                 |              |                  |                   |                  |                  |               |
|---------------|---------------|-----------------|--------------|------------------|-------------------|------------------|------------------|---------------|
| UL - Loi<br>D | Section<br>25 | Township<br>17S | Range<br>34E | Feet from<br>660 | N/S Line<br>North | Feet From<br>860 | E/W Line<br>West | County<br>Lea |
|---------------|---------------|-----------------|--------------|------------------|-------------------|------------------|------------------|---------------|

Well Status

|             |                           |                           |                           |                        |
|-------------|---------------------------|---------------------------|---------------------------|------------------------|
| Well Status | SHUT-IN<br><i>Shut in</i> | PRODUCING<br><i>W I W</i> | DATE<br><i>03/09/2013</i> | <i>Active Injector</i> |
|-------------|---------------------------|---------------------------|---------------------------|------------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A) Surf-Interm | (B) Interm(1)-Interm(2) | (C) Interm-Prod | (D) Prod Casing | (E) Tubing |
|----------------------|-----------------|-------------------------|-----------------|-----------------|------------|
| Pressure             |                 |                         |                 |                 |            |
| Flow Characteristics |                 |                         |                 |                 |            |
| Puff                 | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Steady Flow          | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Surges               | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Down to nothing      | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Gas or Oil           | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Water                | Y / N           | Y / N                   | Y / N           | Y / N           |            |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

*Well is down - have a +bg Leak. back flowing well*

*failure,*

*ELG/ocd 4-11-2013*

|                                               |                           |
|-----------------------------------------------|---------------------------|
| Signature: <i>AL Lujan</i>                    | OIL CONSERVATION DIVISION |
| Printed name: <i>AL Lujan</i>                 | Entered into RBDMS        |
| Title: <i>Lease operator</i>                  | Re-test                   |
| E-mail Address: <i>al-lujan@xtoenergy.com</i> |                           |
| Date: <i>03/12/2013</i>                       |                           |
| Phone: <i>575-414-1638</i>                    |                           |
| Witness:                                      |                           |

APR 17 2013

*h*