

APR 15 2013

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

|                                             |                            |
|---------------------------------------------|----------------------------|
| Operator Name<br>XTO Energy, Inc            | API Number<br>30-025-04432 |
| Property Name<br>Eunice Monument South Unit | Well No.<br>138            |

7. Surface Location

|               |               |                 |              |                  |                   |                  |                  |               |
|---------------|---------------|-----------------|--------------|------------------|-------------------|------------------|------------------|---------------|
| UL - Lot<br>A | Section<br>36 | Township<br>20S | Range<br>36E | Feet from<br>660 | N/S Line<br>North | Feet From<br>660 | E/W Line<br>East | County<br>Lea |
|---------------|---------------|-----------------|--------------|------------------|-------------------|------------------|------------------|---------------|

Well Status

|             |         |           |      |
|-------------|---------|-----------|------|
| Well Status | SHUT-IN | PRODUCING | DATE |
|-------------|---------|-----------|------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Casing   | (E)Tubing |
|----------------------|----------------|------------------------|----------------|------------------|-----------|
| Pressure             |                | 230                    |                | 130              | 739       |
| Flow Characteristics |                |                        |                |                  |           |
| Puff                 | Y / N          | Y / <del>N</del>       | Y / N          | Y / <del>N</del> |           |
| Steady Flow          | Y / N          | Y / <del>N</del>       | Y / N          | Y / <del>N</del> |           |
| Surges               | Y / N          | Y / <del>N</del>       | Y / N          | Y / <del>N</del> |           |
| Down to nothing      | Y / N          | <del>Y</del> / N       | Y / N          | <del>Y</del> / N |           |
| Gas or Oil           | Y / N          | Y / <del>N</del>       | Y / N          | Y / <del>N</del> |           |
| Water                | Y / N          | Y / <del>N</del>       | Y / N          | Y / <del>N</del> |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

Blew down in less than 10 sec.

ELG/ced 4-17-2013

|                                |                           |
|--------------------------------|---------------------------|
| Signature: <i>Luis Cebello</i> | OIL CONSERVATION DIVISION |
| Printed name: Luis Cebello     | Entered into RBDMS        |
| Title:                         | Re-test                   |
| E-mail Address:                |                           |
| Date:                          | Phone:                    |
| Witness:                       |                           |

APR 22 2013