

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23865
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well Number LJU 13 WIW
9. OGRID Number 188483
10. Pool name or Wildcat LANGLIE MATTIX

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐ WIW

2. Name of Operator
PHOENIX HYDROCARBONS OPERATING CORP

3. Address of Operator
P O BOX 3638, MIDLAND, TX 79702 432-686-9869

4. Well Location

Unit Letter F : 1980 feet from the NORTH line and 1980 feet from the WEST line

Section 31 Township 24-S Range 37-E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3243' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: MIT XX


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/24/03 Called Buddy Hill w/NMOCD to inform him that we were doing a T/A Status on well Mr Hill was in Hobbs, NM office and instructed me to proceed.

Opened tbg valve, had 350 psi, bled off, open csg valve, no pressure; RU pump truck started pumping, valve threads on csg valve bad, closed valve, took bull plug off & put nipple and valve on casing head, loaded csg w/3 barrels pkr fluid, pressure held; RU chart recorder, pressured csg up to 540 psi, dropped 20 psi in 30 min, chart attached.

This Approval of Temporary
Abandonment Expires

6/26/2008



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Chris Mitchell TITLE Field Engineer

DATE 6/24/03

Type or print name CHRIS MITCHELL

E-mail address:

Telephone No. 432-686-986

(This space for State use)

APPROVED BY Gay W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JUN 26 2003

Conditions of approval, if any:

