

APR 19 2013

RECEIVED

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28926
Property Name Seven Rivers Queen Waterflood, North	Well No. 13

7. Surface Location

UL - Lot K	Section 4	Township 22S	Range 36E	Feet from 1325	N/S Line South	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING WIW	DATE 3/13/13
-------------	---------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	140	510
Flow Characteristics					
Pull	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Down to nothing	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ☒	FRESH	SALTY	SULFUR	BLACK
---	-------	-------	--------	-------

Remarks:

D) Bleed down in less than 5 secs. Dripped for 45 secs.

Signature: <i>David K Jones</i>	OIL CONSERVATION DIVISION
Printed name: David K Jones	Entered into RBDMS
Title: Lease Operator	Re-test
E-mail Address: david-jones@theenergy.com	
Date: 3/13/13	Phone: 575 411 1627
Witness:	

APR 29 2013