

District 1  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

APR 29 2013

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24594
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot N	Section 36	Township 16S	Range 34E	Feet from 460	N/S Line South	Feet From 1980	E/W Line West	County Lea
---------------	---------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status <i>A</i>	SHUT-IN	PRODUCING <i>INT A</i>	DATE 04-17-2013
-------------------------	---------	---------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Csgng	(E) Tubing
Pressure	0	n/a	0	0	3300
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tested by Eddie Elliott 432-413-0429  
Reported by Trish Mealand 575-623-8424

*ELG/ced 4-29-2013*

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: <a href="mailto:pmealand@limerockresources.com">pmealand@limerockresources.com</a>	
Date: 04-23-2013	Phone: 575-623-8424
Witness:	

MAY 06 2013

*f*