

APR 29 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	APF Number 30-025-24220
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot N	Section 2	Township 17S	Range 34E		Feet from 660	N/S Line South	Feet From 1980	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	--	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING A	DATE 04-17-2013
------------------	---------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0		0	50	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature 	Oil Conservation Division Entered into RBDMS
Printed name: Trish Mealand	Re-test
Title: Production Analyst	
E-mail Address: pmcaland@limerockresources.com	
Date: 04-23-2013	Phone: 575-623-8424
	Witness:

ELG/OCD 4-29-2013

MAY 03 2013