

APR 29 2013

RECEIVED

District I

1625 N French Dr, Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24631
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot 2	Section 1	Township 17S	Range 34E	Feet from 800	N/S Line North	Feet From 2120	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status <i>A</i>	SHUT-IN	PRODUCING <i>INT</i> A	DATE 04-17-2013
-------------------------	---------	---------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	0	0	3300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmealand@limerockresources.com	
Date: 04-23-2013	Phone: 575-623-8424
Witness:	

MAY 06 2013