

APR 29 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-25059
Property Name North Vacuum ABC North Unit	Well No. #001

2. Surface Location

UL - Lot D	Section I	Township 17S	Range 34E	Feet from 860	N/S Line North	Feet From 660	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status <i>A</i>	SHUT-IN	PRODUCING <i>INT</i> ^A	DATE 04-17-2013
-------------------------	---------	--------------------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0	n/a	n/a	0	400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	ELG/OCD 4-29-2013
Printed name: Trish Mealand	OIL CONSERVATION DIVISION
Title: Production Analyst	Entered into RBDMS
E-mail Address: pmicaland@limerockresources.com	Re-test
Date: 04-23-2013	
Phone: 575-623-8424	
Witness:	

MAY 06 2013