

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS C
APR 29 2013
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-34356
Property Name North Vacuum ABO North Unit	Well No. #163

7. Surface Location

UL - Lot M	Section 36	Township 16S	Range 34E	Feet from 660	N/S Line South	Feet From 660	E/W Line West	County Lea
---------------	---------------	-----------------	--------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING A	DATE 04-17-2013
------------------	---------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0		0	50	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cement was circulated to surface during original completion on surface casing.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmealand@linerockresources.com	
Date: 04-23-2013	Phone: 575-623-8424
Witness:	

ELG/oco 4-29-2013

MAY 06 2013

h