

HOBBS OCD

APR 30 2013

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-33146
Property Name North Vacuum ABO North Unit	Well No. #194

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
G	2	17S	34E	1980	North	1980	East	Lea

Well Status

Well Status	SHUT-IN	PRODUCING A	DATE 04-17-2013
-------------	---------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Csg	(E) Tubing
Pressure		N/A	50	50	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

Intermediate bled to 0 in 5 mins. Csg bled down with intermediate suspect leak in csg at wellhead. Called Maxie Brown with NMOCD, was instructed to shut well in.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

ECG/OOD 5-2-2013

Signature: 	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmealand@limerickresources.com	
Date: 04-23-2013	Phone: 575-623-8424
Witness:	

MAY 06 2013