

Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

Energy, Minerals and Natural Resources

Revised August 1, 2011

HOBBS OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

FEB 21 2013

WELL API NO. 30-025-25894
5. Indicate Type of Lease Federal <input checked="" type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-6863
7. Lease Name or Unit Agreement Name Querecho Plains Bone Spring Sand Unit
8. Well Number QPBSSU 8 #1
9. OGRID Number 14744
10. Pool name or Wildcat Querecho Plains-U. Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other Injection Well

2. Name of Operator
Mewbourne Oil Company

3. Address of Operator
PO Box 5270, Hobbs, NM 88240

4. Well Location
Unit Letter K : 1980' feet from the South line and 1980' feet from the West line
Section 27 Township 18S Range 32E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3727.7' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER:

OTHER: Integrity Test

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

An integrity test and braden head test were performed on the QPBSSU 8 #1, OK. This well is included in the Mewbourne Oil Company's Querecho Plains Waterflood. This test was performed on Feb. 12, 2013. Donna Mull with the NMOCD was notified but did not witness. The chart for this test is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Antonio Martinez*

TITLE Engineer

DATE 2-19-2013

Type or print name Antonio Martinez

E-mail address: amartinez@mewbourne.com PHONE: (575) 393-5905

For State Use Only


APPROVED BY: *Dist. Mar*

TITLE Dist. Mar

DATE 5-14-2013

Conditions of Approval (if any):

MAY 21 2013 *[Signature]*



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

Newhome Oil Company
QPBSUB #1
K-27 185-32E
30-025-25894

2/12/2013

BR 2221

1-40
1000 ft/min
Calib 9/20/2012