

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

APR 03 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corporation	API Number 30-025-05667
Property Name NMGSAU	Well No. 2811

Surface Location

UL - Lot K	Section 20	Township 19S	Range 37 E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County Lea
---------------	---------------	-----------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING (inj)	DATE
------------------	---------	--------------------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm Csng	(D)Prod Csng	(E)Tubing
Pressure	0		0	710	725
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(D) bled down water to zero in one minute

Signature: 	ELG/OCD 5-14-2013 OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Technician	Re-test
E-mail Address: JD.Ellison@apachecorp.com	
Date:	
Phone: 575-441-7734	
Witness:	

MAY 21 2013