<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

Title: Engineer

Date: 4/17/13

Tested by Allon Dobbs

E-mail Address: cdoranhaynes@jhhc.org

Phone: 432-684-6631

Witness:

## **State of New Mexico**

MAY 1 4 2013

## **Energy, Minerals and Natural Resources Department**

	Oil Conservation Division Hobbs District Office						RECEIVED		
				BRADENI	HEAD TES	T REPORT	•	1	
			Operator 1	Vame				<sup>3</sup> API Numbe 3002524279	
_			John H. Hendrix				<u> </u>		
Property Name								Well No.	
	Cossatot F							001	
	,			7. Su	rface Locatio	n			
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
С	23	22S	37E		330	N	1980	w	Lea
				V	Vell Status			_	
	Well Status / SHUT-IN Active				PRODUCING P		DATE 04/17/13		
	OPE	N BRADEN	HEAD AND INT	ERMEDIATE T	O ATMOSPHEI	RE INDIVIDUAL	LY FOR 15 MINUT	ES EACH	
OBSERVED DATA  f bradenhead flowed water, check all of the descriptions that apply:									
		(A)S	urf-Interm	(B)Interm(1)-I	nterm(2)	(C)Interm-Prod	(D)Pro	od Csng	(E)Tubing

	(A)Sull-Interin	(D)Internit I - Internit 21	(C) intering 1 rou	(D)I Tou Csing	(L) rubing
Pressure	5			24	<u>26</u>
Flow Characteristics					
Puff	(Y) N	Y / N	Y / N	Y / N	
Steady Flow	Y/N	Y / N	Y / N	Y/N	
Surges	Y / N	Y/N	Y/N	Y / N	
Down to nothing	(Y) N	Y/N	Y/N	Y / N	_
Gas or Oil	Y/(N)	Y/N	Y/N	Y / N	
Water	Y/N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK		
Remarks:						
5# – puff down to n	othing					
		,				
	ary walk		/			
ľ	9		AGIONA	5-14-201		
Signature: aroly Dra Jayru				OIL CONSERVATION DIVISION		
Printed name: Carolyn Doran Haynes			Entered into RBDMS			

Re-test