

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 14 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name John H. Hendrix Corporation	API Number 30025244340000
Property Name Sun Dangle	Well No. 5

7. Surface Location

UL - Lot K	Section 13	Township 22S	Range 37E	Feet from 1650	N/S Line S	Feet From 1980	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status Active	SHUT-IN	PRODUCING P	DATE 04/17/13
-----------------------	---------	----------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	22			14	14
Flow Characteristics					
Puff	[Y] N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	[Y] N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	[Y] N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

22# - spray with a small amount of water - bled down to nothing in 35 seconds - less than a cup in 24 hours

Carolyn Doran Haynes

Signature: <i>Carolyn Doran Haynes</i>	OIL CONSERVATION DIVISION
Printed name: Carolyn Doran Haynes	Entered into RBDMS
Title: Engineer	Re-test
E-mail Address: cdoranhaynes@jhhc.org	
Date: 4/17/13	Phone: 432-684-6631
Tested by Allon Dobbs	Witness:

ECG/OCD 5-14-2013

MAY 22 2013

h