Submit One Copy To Appropriate District	State of New Mexico	/ Form C-103
Office	nergy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	neigy, willierars and ivalurar resources	WELL API NO. 30-025-08008
	OIL CONSERVATION DIVISION	
88210 HOB3S O	CD ₁₂₂₀ South St. Francis Dr.	5. Indicate Type of Lease STATE FEE □
1000 Die Deerse Dd. Artes NM 97410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM MAY 16 87505	2013	B1-0278-0004
		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALES FO DIFFERENT RESERVOIR. USE "APPLICATION I		New Mexico BH State
PROPOSALS.) 1. Type of Well: ⊠Oil Well ☐ Gas Well	ell 🔲 Other	8. Well Number 002
2. Name of Operator		9. OGRID Number
PALADIN ENERGY CORP.		164070
3. Address of Operator 10290 Monroe Drive, Suite 301, Dallas, Te	exas 75229	10. Pool name or Wildcat 09310 Caprock; Wolfcamp, East
4. Well Location		/ /
Unit Letter F: 1980 feet from the North line and 1980 feet from the West line		
Section 11 Township 12S Range 32E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
·	IGE PLANS 🔲 COMMENCE DR	ILLING OPNS.□ P AND A □
PULL OR ALTER CASING MULT	TIPLE COMPL CASING/CEMEN	T.JOB · · · · · · □ · · ·
OTHER:		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 		
Pipelines and flow lines have been aban retrieved flow lines and pipelines.	doned in accordance with 19.13.33.10 NWAC	. All fluids have been removed from non-
When all work has been completed, return th	is form to the appropriate District office to scl	nedule an inspection.
SIGNATURE ()) Tens	TITLE Margan Como	DATE 05/12/12
SIGNATURE		
TYPE OR PRINT NAME Ann Westberry E-MAIL: _awestberry@paladinenergy.com PHONE: _214-654-0132 X4 For State Use Only		
$\sqrt{\sqrt{2}}$		
APPROVED BY:	TITLE COMPULM	DATE SICOLAN
Conditions of Approval (if any).	•	1 8