

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                          |                              |
|------------------------------------------|------------------------------|
| Operator Name<br>OCCIDENTAL PERMIAN, LTD | API Number<br>30-025-31421 ✓ |
| Property Name<br>SOUTH HOBBS (G/SA) UNIT | Well No.<br>230 ✓            |

2. Surface Location

|                |              |                  |               |                   |                   |                   |                  |                 |
|----------------|--------------|------------------|---------------|-------------------|-------------------|-------------------|------------------|-----------------|
| U/L - Lot<br>B | Section<br>4 | Township<br>19-S | Range<br>38-E | Feet from<br>1100 | N/S Line<br>NORTH | Feet From<br>2220 | E/W Line<br>EAST | County<br>LEA ✓ |
|----------------|--------------|------------------|---------------|-------------------|-------------------|-------------------|------------------|-----------------|

Well Status

|                  |         |                  |                 |                  |
|------------------|---------|------------------|-----------------|------------------|
| Well Status<br>A | SHUT-IN | PRODUCING<br>INT | DATE<br>4-26-13 | Active Water Int |
|------------------|---------|------------------|-----------------|------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Casing | (E)Tubing |
|----------------------|----------------|------------------------|----------------|----------------|-----------|
| Pressure             | PLFF           | NA                     | NA             | 2              | 1648      |
| Flow Characteristics |                |                        |                |                |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N          |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N          |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N          |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N          |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N          |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N          |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

Surface Puff to 2

HOBBS OCD

MAY 20 2013

RECEIVED

Seal Wellhead

|                                       |                           |
|---------------------------------------|---------------------------|
| Signature: <i>Mendy Johnson</i>       | ELG/POD 5-20-2013         |
| Printed name: MENDY JOHNSON           | OIL CONSERVATION DIVISION |
| Title: ADMINISTRATIVE ASSOCIATE       | Entered into RBDMS        |
| E-mail Address: mendy.johnson@oxy.com | Re-test                   |
| Date: 5/17/2013                       |                           |
| Phone: 806-592-6280                   |                           |
| Witness:                              |                           |

MAY 29 2013