JUN 1 3 2013

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phona: (575) 393-6161 (fax: (575) 393-0720

RECEIVED

30-025-33945

State of New Mexico

E nent e

BRADENHEAD TEST REPORT

inergy, Minerals an	id Natura	l Resources	Departn
Oil Conservation	Division 1	Hobbs Dist	rict Office

Operator Name

Reserves

		7. Surface Locat	tion				
VIL-Lot Section Too	Range 37E	Feet from /308	N/S Line S	Feet From 2502	E/V Line	County	
Well Status							
Well Status A	SHUT-IN	PRODUCING C	7/5/	Q1/13			
OPEN BR	ADENHEAD AND INT	ERMEDIATE TO ATMOSPH	ERE INDIVIDUALLY	Y FOR 15 MINUT	ES EACH		
If bradenhead flowed water, e	heck all of the description	OBSERVED DA	ATA				
	(A)Suri-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Proc	l Csng	(E) Tubing	
Pressure	Q				6 Ô	60	
Flow Characteristics							
Puff	(Y)/ N	YIN	Y7 N		Y / N	1	
Steady Flow	Y 7(N)	Y/N	Y / N	1	Y/N	1	
Surges	Y 7 (N)	Y/N	Y7 N	1	Y/N		
Down to nothing	W/N W/N	Y/N	Y/N	ŀ	Y/N		
Gas or Oil Water	Y/(N)	Y/N Y/N	Y/N Y/N		Y / N Y / N		
, raici	1 (0)	171	1,11				
If bradenhead flowed water, check all of the descriptions that apply:							
CLEAR	FRESH	SALTY	SULFU	₹	BLACK		
Remarks:							
Signature: A.		**************************************		(G/000	6-13	-2013	
OIL CONSERVATION DIVISION				n division			
Printed name: Stoven D. Honan			1	Entered into RBDMS			
Title: Re-test							
E-mail Address:			PARTICIPATION	· · · · · · · · · · · · · · · · · · ·		SPACE	
Date: 5/21/1	Phone:		ang sabet libe.			T. T	
	Witness:		att Tracti			· ·	
JUN 17 2013							