

District I  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

JUN 03 2013

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	API Number 30-025-10533
Property Name SKELLY PENROSE B UNIT	Well No. 11

7. Surface Location

UL - Lot 1	Section 31	Township 22S	Range 37E	Feet from 1980	N/S Line SOUTH	Feet From 330	E/W Line EAST	County LEA
---------------	---------------	-----------------	--------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING A-OIL	DATE 05/10/2013
-------------	---------	--------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0#			30#	30#
Flow Characteristics					
Puff	Y	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	N	Y / N	Y / N	Y - N	
Down to nothing	(Y) / N	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Y / N	Y / N	
Water	N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Braiden Head - 2 - 3 second blow with no fluid.

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test
E-mail Address: providenceenergy@suddenlink.net	
Date: 05/30/2013	Phone: 432-661-1364
Witness:	

ELG/OCD 6-3-2013

JUN 18 2013