

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

JUN 03 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	API Number 30-025-10627
Property Name SKELLY PENROSE B UNIT	Well No. 17

7. Surface Location

UL - Lot D	Section 4	Township 23S	Range 37E	Feet from 660	N/S Line NORTH	Feet From 660	E/W Line WEST	County LEA
---------------	--------------	-----------------	--------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING A - INJ	DATE 05/10/2013
-------------	---------	----------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0#			80#	305#
Flow Characteristics					
Puff	N	Y / N	Y / N	Y	
Steady Flow	Y / N	Y / N	Y / N	N	
Surges	Y / N	Y / N	Y / N	N	
Down to nothing	Y / N	Y / N	Y / N	Y	
Gas or Oil	Y / N	Y / N	Y / N	N	
Water	Y / N	Y / N	Y / N	Y	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(D) Prod Casing: Casing had black emulsion at valve. Cracked casing valve - blew down in 6-10 seconds.

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test
E-mail Address: providenceenergy@suddenlink.net	
Date: 05/30/2013	Phone: 432-661-1364
Witness:	

JUN 18 2013