State of New Mexico Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

JUN 0 3 2013

RECEIVED

ŧ

BRADENHEAD TEST REPORT

	Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating						· 30-025-10626		
			Property SKELLY PE	y Name NROSE B UNIT	/		Well No. 30		
				^{7.} Surface Location	<u></u>		<u> </u>		
UL - Lot E	Section 4	Township 23S	Range 37E	Feet from 1980	N/S Line NORTH	Feet From 660	E/W Line WEST	County LEA	
				Well Status		·			

Well Status SHUT-IN PRODUCING DATE A - INJ 05/10/2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	<u>0#</u>			0#	310#
Flow Characteristics					
Puff	N	Y/N	¥7 N		
Steady Flow	Y/N	Y / N	Y7N		
Surges	Y/N	Y / N	Y/N	N	
Down to nothing	Y/N	Y / N	Y/N		
Gas or Oil	N	Y / N	Y / N	N	
Water	N	Y/N	Y/N	Y	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
Remarks:	er for 45 seconds and stoppe	đ		
Casing on ppeorecar was		u.		
				/
			EGA	DAD 6-3-2013
Signature:	Darla			INSERVATION DIVISION
Printed name: C. DALE	KELTON		Entered into	RBDMS
Title: PRESIDENT			Re-test	
E-mail Address: provide	ncecnergy@suddenlink.net			
Date: 05/30/2013	Phone: 432-0	561-1364		
l	Witness:			
				JUN 1 8 2013

HOBBS OCD