	'			
Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources			May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lea	80-025-09628
District III	1220 South St. Francis Dr.		STATE	FEE 🔀
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Leas	
1220 S. St. Francis Dr., Santa Fe, NM 87505			NM 12612	
	ICES AND REPORTS ON W	ELLS	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPO				
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)			NM 70926X	
1. Type of Well: Oil Well	Gas Well 🗌 Other	Injector	8. Well Number Coope	
2. Name of Operator			9. OGRID Number	193003
3. Address of Operator	SDG Resources L. P. P. O. Box 1390	······	10. Pool name or Wildo	cat JALMAT:
3. Address of Operator	Montrose, CO 81401		Tansill, Yates & 7-Rive	
4. Well Location		<u></u>		
Unit Letter A	: 660 feet from theNO	RTH line and3	30feet from theI	EASTline
Section 24	Township 24S	Range 36E	NMPM LEA	County
- The second sec	11. Elevation (Show wheth)	
		316' KB	1000	
Pit or Below-grade Tank Application		C 1	Di 4	
Pit type_DIRTDepth to Groundwater_				water_>IVVV leet
Pit Liner Thickness: 12 mil Below-Grade Tank: Volume 200 bbls; Construction Material Synthetic				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				IDA 🗌
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/CEMENT JOB				
OTHER: OTHER: Redressed packer & replaced 3 joints of tubing.				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
Objective: Redressed packer and replaced 3 bad joints of tubing.				
 MIRU Pulling Unit. POOH with 2 3/8" cement lined tubing and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. 				
3. Redressed 5 ½" x 2 38" Baker AD-1 packer. Hydrotest cement lined tubing in hole. Found and replaced 3 joints tubing.				
 or recompletion. Objective: Redressed packer and replaced 3 bad joints of tubing. 1. MIRU Pulling Unit. 2. POOH with 2 3/8" cement lined tubing and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. 3. Redressed 5 ½" x 2 38" Baker AD-1 packer. Hydrotest cement lined tubing in hole. Found and replaced 3 joints tubing. 4. Circulate annulus with inhibited packer fluid. 5. Set packer and test annulus to 400 psig for 30 minutes. Pull chart for NMOCD. 				
 6. Place well on injection at approximately 200 bwpd. Maximum permitted injection pressure is 600 psig. 7. Recovered and disposed of pit water. 				
8. Fold Pit Liner inward, cover w		top soil. File Form C144	with NMOCD.	all
				2929292
I hereby certify that the information	n above is true and complete to	the best of my knowled	ge and belief. I further certi	fy that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].				
SIGNATURE	Canyota T	ITLESenior Petroleun	n Engineer	_DATE_10/05/05_
Type or print name Domingo Carrizales E-mail address: Domingo@sdgresources.com Telephone No. 432-580-8500				
APPROVED BY Law Wink OC FIELDTREPRESENTATIVE II/STAFF MANAGER DATION 1 1 2005				
APPROVED BY Law W. Wink OCFIETETREPRESENTATIVE INSTANT DATECT 1 1 2005				
Conditions of Approval (2 any):	UC TILLD			
			1	



•

