

JUN 19 2013

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

## BRADENHEAD TEST REPORT

|                                          |                            |
|------------------------------------------|----------------------------|
| Operator Name<br>OCCIDENTAL PERMIAN, LTD | API Number<br>30-025-07572 |
| Property Name<br>SOUTH HOBBS (G/SA) UNIT | Well No.<br>6              |

## 7. Surface Location

|               |               |                  |               |                  |                   |                  |                  |               |
|---------------|---------------|------------------|---------------|------------------|-------------------|------------------|------------------|---------------|
| UL - Lot<br>M | Section<br>34 | Township<br>18-S | Range<br>38-E | Feet from<br>660 | N/S Line<br>SOUTH | Feet From<br>660 | E/W Line<br>WEST | County<br>LEA |
|---------------|---------------|------------------|---------------|------------------|-------------------|------------------|------------------|---------------|

## Well Status

|                    |         |           |                   |              |
|--------------------|---------|-----------|-------------------|--------------|
| Well Status<br>T&A | SHUT-IN | PRODUCING | DATE<br>6/11/2013 | T&A Producer |
|--------------------|---------|-----------|-------------------|--------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A) Surf-Interm | (B) Interm(1)-Interm(2) | (C) Interm-Prod | (D) Prod Casing | (E) Tubing |
|----------------------|-----------------|-------------------------|-----------------|-----------------|------------|
| Pressure             | 0               | 15                      | 75              | 25              |            |
| Flow Characteristics |                 |                         |                 |                 |            |
| Puff                 | Y/N             | Y/N                     | Y/N             | Y/N             |            |
| Steady Flow          | Y/N             | Y/N                     | Y/N             | Y/N             |            |
| Surges               | Y/N             | Y/N                     | Y/N             | Y/N             |            |
| Down to nothing      | Y/N             | Y/N                     | Y/N             | Y/N             |            |
| Gas or Oil           | Y/N             | Y/N                     | Y/N             | Y/N             |            |
| Water                | Y/N             | Y/N                     | Y/N             | Y/N             |            |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |     |
|-------|-------|-------|--------|-------|-----|
| CLEAR | FRESH | SALTY | SULFUR | BLACK | yes |
|-------|-------|-------|--------|-------|-----|

Remarks:

No pressure on surface  
oil, water on int, need Truck

Mendy Johnson

ECG/OCD 6-19-2013

|                                       |                           |
|---------------------------------------|---------------------------|
| Signature: Mendy Johnson              | OIL CONSERVATION DIVISION |
| Printed name: MENDY JOHNSON           | Entered into RBDMS        |
| Title: ADMINISTRATIVE ASSOCIATE       | Re-test                   |
| E-mail Address: mendy_johnson@oxy.com |                           |
| Date: 6/17/2013                       | Phone: 806-592-6280       |
| Witness:                              |                           |

JUL 08 2013