

Mesquite Services BH Tests 7/09/2013

Inge, Richard, EMNRD

Sent: Tuesday, July 09, 2013 4:03 PM

To: Dickey, Sylvia, EMNRD

Sylvia,

I tested the following 3 wells for Mesquite Services today:

Paducha SWD 001	30-025-27616	Tubing 700, Surface – puff, Casing – no pressure	
Paducha Fed SWD 002	30-025-40813	Tubing 400, Surface – no pressure, Casing – no pressure	
West Jal Disposal - puff	30-025-26676	Tubing, 190, Surface – no pressure, Intermediate - no pressure, Casing - puff	

Richard Inge
Compliance Officer
NMOCD – Artesia District Office
575-748-1283x107 – office
575-626-0831 - cell

JUL 15 2013