Submit   Copy To Appropriate District State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283         811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178         1000 Bis Derme Bd. Antes NM 97(10)	30-005-00874
Bit S. First St., Artesia, NM 88210 District III – (505) 334-6178 HOBBS OCD 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE STATE
1000 KIO Brazos Rd., Azlec, NM 87410 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMUL <b>1 8 2013</b> 87505	303735
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS (TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Rock Queen Unit
PROPOSALS.)	8. Well Number 49
2. Name of Operator Celero Energy II, LP	9. OGRID Number
3. Address of Operator 400 W. Illinois, Ste. 1601	247128 10. Pool name or Wildcat
Midland, TX 79701	Caprock; Queen
4. Well Location	
Unit Letter O       : 660       feet from the South       line and 1980       feet from the East       line         Section 26       Township 13S       Range 31E       NMPM       County Chaves	
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMEN COWNHOLE COMMINGLE	I JOB
OTHER: OTHER: OTHER: OTHER:	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
7/9/13 - Ran and set 1,562 "R" blanking plug in profile nipple at 2985'. Placed 200 psi on tbg to help seat plug.	
7/10/13 - Test tbg-csg annulus to 550 psi FS to 2971'. Held 10 mins & no pressure loss. Rel on/off tool from pkr & circ hole w/ PW. TOH w/ 2 3/8" IPC tbg w/ T-2 on/off tool. Pull 91 jts w/ 2 - 10' x 2 3/8" tbg subs & Globe Energy's top assembly. PU 2 7/8" tbg WS w/ 2 7/8" perf nipple & 0/0 tool. TIH & latch onto pkr at 2971'. Release pkr & TOH w/ tbg & pkr. TIH w/ 4 3/4" bit, 1 - 3 1/8" DC, 4 7/8" string mill, 1 - 3 1/8" DC, 4 7/8" string mill., 1 3 1/8" DC, & ran on 2 7/8" tbg WS. Tag at $3050' = TD$ .	
7/11/13 - Lower bit back to bottom & circ hole clean. No fill with very little cuttings. Pumped 500 gals of Xylene down tbg back up	
tbg-csg annulus. Rev pump back down tbg-csg annulus, back up tbg-csg annulus. Pumper into formation with 50 +/- BPW. Pumped away at 200 psi & 2+ BPM. SD psi = 140 psi.	d Xylene back down csg and overflushed Let set 30 mins and pressure bled off. TOH
w/ tbg WS, LD tbg with DC's, string mills and bit. The BHA was clean. RU to run 5 1/2"	cap string pkr and 2 3/8" IPC tbg. Ran 91
jts of 2 3/8" OD 4.7# 8rd EUE J-55 IPC tbg with 5 1/2 " NP AS1-X pkr w/ 1.562 "R" blanking plug in profile nipple. Set pkr from 2969' to 2982'. *Continued on attached sheet	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.
SIGNATURE Jan Hund TITLE Regulatory Analyst	DATE 07/16/2013
Type or print name       Lisa Hunt         For State Use Only       Image: Comparison of the second se	rgy.com PHONE: <u>(432)686-1883</u>
APPROVED BY:	DATE 7-22/20/3
Conditions of Approvation any.	JUL 2 4 2013

.

## Rock Queen Unit #49 – C103 continued

7/12/13 - Release from pkr. Circ hole with pkr fluid. TOH w/ tbg and T-2 on/off tool. PU Globe Energy's Top Assembly ran on 91 jts of 2 3/8" OD 4.7# 8rd EUE seal lube IPC tbg plus 2 - 3/8" SS cap strings banded to the 2 3/8" tbg. Latch onto to pkr at 2969'. Install 7 1/16" 3K slip type flange with 2 - 1" outlets w/ stuffing boxes for the 3/8" SS cap strings. Tied onto CO2 & chemical/water cap strings & pumped 12 gallons of fresh water down each. Placed 10 pts compression on pkr. Finish connecting up WH, installed 2 1/16" 5K full opening valve. Equalized 1,562 "R" blanking plug in profile nipple. TIH and recovered blanking plug. Return well to production.