

District 1
1624 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

JUL 25 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.		API Number 30-025-30736	
Property Name East Corbin Delaware Unit		Well No. 6	

Surface Location

UL - Lot C	Section 21	Township 18S	Range 33E	Feet from 779	N/S Line North	Feet From 1943	E/W Line West	County Lea
---------------	---------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status Shut-in	SHUT-IN	PRODUCING	DATE
------------------------	---------	-----------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure				0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Well is not in use due to a hole in the tubing.

Field information submitted by Hector Serna.

7/30/2013
Letter of Violation
due to hole in tubing
as noted. LHS

Signature: <i>Stan Wagner</i>		OIL CONSERVATION DIVISION	
Printed name: Stan Wagner		Entered into RBDMS	
Title: Regulatory Analyst		Re-test	
E-mail Address: stan.wagner@eoqresources.com			
Date: 7/25/2013	Phone: 432-686-3689		
Witness:			

JUL 31 2013