Submit One Copy To Appropriate District Office <u>District 1</u>	State of New Me Energy, Minerals and Natu		Form C-103 Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88240 1 2 2013 OIL CONSERVATION DIVISION			WELL API NO. 30-025-28063
District III 1220 South St. Francis Dr.			5. Indicate Type of Lease STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NMRECEIVED 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			JF Janda NCT-L
1. Type of Well: XOil Well Gas Well Other			8. Well Number 001
2. Name of Operator Quantum Resources Management, LLC			9. OGRID Number 243874
3. Address of Operator 1401 McKinney Street; Ste. #2400, Houston, TX 77010			10. Pool name or Wildcat Jalmat; Tan-Yates-7Rvrs (Oil)
4. Well Location			
Unit Letter <u>D</u> : <u>330</u> feet from the <u>N</u> line and <u>990</u> feet from the <u>W</u> line			
Section 36 Township 22S_Range 35E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3549' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
PULL OR ALTER CASING		CASING/CEMENT	
OTHER: I Kertion is ready for OCD inspection after P&A			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the 			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
<u>PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
to be removed.) Image: Second state of the second state			
EX Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Uluta A. Jak TITLE Sr. Regulatory Analyst DATE 07/01/13			
TYPE OR PRINT NAME Celeste G. Dale E-MAIL: cdale@gracq.com PHONE: 432-683-1500 For State Use Only C C			
APPROVED BY: Mahwhitch TITLE Compliance Officer DATE 07/31/13			
		1	

AUG 0 1 2013

grev