

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

JUL 30 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.	API Number 30-025-39705
Property Name Lomas Rojas 26 State Com	Well No. 6

Surface Location

UL - Lot G	Section 26	Township 25S	Range 33E	Feet from 2620	N/S Line North	Feet from 1810	E/W Line East	County Lea
---------------	---------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status Active	SHUT-IN Active	PRODUCING SWD	DATE 7/23/13
-----------------------	-------------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0		0	50	1344
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

- (C) No pressure
(D) Had 50 psi, opened casing and blew down to 0 in 20 seconds.

Well active during test.

Letter of Violation
Due to over
Injection Pressure.
GAD 8/1/13.

Field information submitted by Paul Corrales

Signature: 	ECG/POD 7-31-2013 OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan.wagner@eoqresources.com	
Date: 7/29/2013	Phone: 432-686-3689
Witness:	

AUG 01 2013