Form 3160-5	
(August 2007)	

51

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs
HOBUS

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. 5. Lease Serial No. NMLC029405B

6. If Indian, Allottee or Tribe Name

abandoned we	II. USE IUIIII 3100-3 (AFD) 1	or such proposais.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agree	ement, Name and/or No.
Type of Well Gas Well Other				8. Well Name and No. RUBY FEDERAL 14	
2. Name of Operator CONOCOPHILLIPS COMPANY E-Mail: Susan.B.Maunder@conocophillips.com				9. API Well No. 30-025-41010-00-X1	
3a. Address 3300 N "A" ST BLDG 6 MIDLAND, TX 79705	 Phone No. (include area code h: 432-688-6913)	10. Field and Pool, or Exploratory MALJAMAR		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State	
Sec 17 T17S R32E NWSE 21		LEA COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	NDICATE NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION		
		Deepen	Productio	on (Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	🗖 Reclama	tion	Well Integrity
🛛 Subsequent Report	Casing Repair	New Construction	🗖 Recompl	ete	🛛 Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Tempora	Temporarily Abandon	
	Convert to Injection	Plug Back	U Water Disposal		
testing has been completed. Final Al determined that the site is ready for f ConocoPhillips Company resp to frac operations. On July 29, 2013 COP pressu reduction of less than 10% in An image of the pressure cha During completion operations backside. Pressure gauge and Thank you for your considerat	inal inspection.) bectfully submits this subsequ are tested the Surf Csg x Prod 32 minutes. Ending pressure rt is attached. we plan on installing a press d monitoring services to be p	uent report of performing o d Csg annulus to 680# wit was 625#. ure gauge and monitor pr	casing test print h a pressure essure on the	or HOB S AUG	IS OCD 07 2013 RECEIVED
14. I hereby certify that the foregoing is	Electronic Submission #215	LLIPS COMPANY, sent to ing by KURT SIMMONS on	the Hobbs 08/01/2013 (13	KMS2509SE)	
Name(Printed/Typed) SUSAN E	3 MAUNDER	Title SR. RE	GULATORY	SPECIALIST	
Signature (Electronic S	Signature (Electronic Submission) Date 07/31/2013				
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	E	
APPTOVED By ACCEPT	ED		FERNANDE		Date 08/05/2013
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the sub		k	2	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED **



Ruby 14 subsequent rpt of casing test submitted

Hale Stra

Maunder, Susan B <Susan.B.Maunder@conocophillips.com> Wed, Jul 31, 2013 at 10:57 AM To: "Chen, James J" <James.J.Chen@conocophillips.com>, "efemand@blm.gov" <efemand@blm.gov> Cc: "Franco, Alva" <Alva.Franco@conocophillips.com>

James and Ed,

I've submitted the subject paperwork and attached it for your convenience. I'm also attaching the chart image to make sure it is part of your record.



Please advise if there is additional information needed.

All the best, Susan

7-31-13 submittedSub't on casing test.pdf 11K

OPERATOR'S NAME:	ConocoPhillips
LEASE NO.:	LC029405B
WELL NAME & NO.:	14 Ruby Federal
LOCATION:	Section 17, T.17 S., R.32 E., NMPM
COUNTY:	Lea County, New Mexico

Conditions of Acceptance

Operator shall monitor the 8-5/8" by 5-1/2" annulus during Frac procedure and have the service company document the pressure during the procedure.

Operator to submit a subsequent report sundry & provide a copy of service company frac report with chart of 8-5/8" by 5-1/2" annulus being monitor.

Several days after the Frac the operator to shall re-test the 8-5/8" by 5-1/2" annulus up to 680 psi with a chart recorder. Operator to keep pressure on the 8-5/8" by 5-1/2" annulus for up to 30 minutes and longer if needed until the pressure stabilizes for at least 10 minutes. Submit to BLM ASAP

EGF 050313