JUL 2 2 2013

30-025-40938 INCLINATION-REPORT

J(J)	22	201	3)
------	----	-----	----

INCLI	NATION:REPORT	DECEIVED	
FIELD NAME	LEASE NAME	Well Number	
Eumont Yates TR Qn	East Eumont Unit	202	
OPERATOR			
DOG RESOURCES OXY USIA WTO LA			
ADDRESS			
LOCATION (Section, Block, and Survey)		County	
1310 FSL 1410 FWL N	3-195-37E	Eddy Lea	
	ORD OF INCLINATION		

RECORD OF INCLINATION						
			Displacement per			
		Angle of	Hundred Feet	Course	Accumulative	
Measured Depth	Course Length	Inclination	(Sine of Angle	Displacement	Displacement	
(feet)	(Hundreds of feet)		X100)	(feet)	(feet)	
349	3.49		0.38	1.34	1.34	
1316		0.4	0.70	6.75	8.09	
2136	8.20	0.9	1.57	12.88	20.97	
3036	9.00	0.5	0.87	7.85	28.82	
3981	9.45	1.3	2.27	21.44	50.26	
4135	1.54	1.3	2.27	3.49	53.76	
	-41.35		0.00	0.00	53.76	
	0.00		0.00	0.00	53.76	
	0.00		0.00	0.00	53.76	
	0.00		0.00	0.00	53.76	
	0.00		0.00	0.00		
	0.00		0.00	0.00		
	0.00		0.00	0.00		
	0.00		0.00	0.00		
	0.00		0.00	0.00		
	0.00	}	0.00	0.00		
·	0.00		0.00	0.00		
	0.00		0.00	0.00	53.76	
	0.00		0.00		53.76	
·	0.00			0.00		
			0.00	0.00		
	0.00		0.00	0.00		
	0.00	Ì	0.00	0.00	53.76	

Accumulative total displacement of well bore at total depth of	>	4135	feet =	53.76
Inclination measurements were made in-	Tubing	Casing	Open Hole	Drill Pipe
Distance from surface location of well to the nearest lease line measured in feet				

Minimum distance to lease line as prescribed by field rules measured in feet -

Was the subject well at any time intentionally deviated from the vertical in an manner whatsoever?

Company

Kendra K. Smith, Admin Coord.

Name of Person and Title (type or print) Helmerich & Payne IDC

Name of Company

Telephone:

(432) 563-5757

Operator

432-685-5717