

AUG 10 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name

API Number

Oxy USA Inc.

30-025-08208

Property Name

Well No.

COTTON DRAW - PADUCAH Unit

#30

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
F	21	T25S	R32E	1980	N	1980	W	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
Active		Yes / water In.	15 MAY 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	700
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Signature:

Donnie Johnson

Printed name:

DONNIE JOHNSON

Title:

PUMPER

E-mail Address:

Donnie Johnson @ oxy.com

Date:

15 MAY 13

Phone:

432-530-7630

Witness:

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

AUG 15 2013