

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised July 18, 2013

RECEIVED

OIL CONSERVATION DIVISION

SEP 30 2013

HOBBSDOCD Santa Fe, NM 87505

WELL API NO. 30-025-30196
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-9519
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT
8. Well Number 108
9. OGRID Number 004115
10. Pool name or Wildcat DOLLARHIDE QUEEN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) KB = 3189'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ INJECTOR

2. Name of Operator
CHAPARRAL ENERGY, LLC.

3. Address of Operator
701 CEDAR LAKE BLVD. OKC, OK 73114

4. Well Location
Unit Letter E : 2310 feet from the NORTH line and 380 feet from the WEST line
Section 29 Township 24S Range 38E NMPM LEA County NM

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: BRADENHEAD TEST ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/17/2013 - FAILED BRADENHEAD TEST.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lindsay Reames TITLE ENGINEERING TECH II DATE 9.30.2013

Type or print name: LINDSAY REAMES E-mail address: lindsay.reames@chaparralenergy.com PHONE: 405.426.4549

For State Use Only

APPROVED BY: [Signature] TITLE Dist. MGR DATE 9-30-2013

Conditions of Approval (if any):

SEP 30 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	API Number 30025301960000
Property Name West Dollar Hide Queen Sand Unit	Well No. 108

Surface Location

UL - Lot 3T	Section 29	Township 24S	Range 38E	Feet from 2310	N/S Line ENL	Feet From 380	E/W Line FWL	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status SHUT-IN	PRODUCING Injection	DATE 9/17/2013
-------------------------------	-------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0				250
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

water coming out of casing - Failed test 9/17/13

Chad Whitaker
Witnessed 9/17/2013;
Notice of Violation 9/19/2013.
SAD 9/30/2013.

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address:	
Date: 9-17-13	Phone: 405-227-4298
Witness:	

KB: 3189.6'

DF:

GL: 3178'

Chaparral Energy, L.L.C.

Well: West Dollarhide QSU ,108 ,4087.05

Operator: CELLC

Location: 2310' ENL & 380' FWL, Lea Co., N

Legal: Sec. 29-24S-38E

County: Lea, NM

LAT/Long: /

Size: 12 1/4"

8 5/8" ,24 #,J-55 @410" ,250 ex

Dir:

Spud Date: 02/08/90

Drilling Finished: 02/12/90

Completion Date: 02/23/90

First Production:

TUBING #1:

Type	#Jts	Size	Wt#/f	Grade	Set@
EUE		2 3/8"			3604

HISTORY:

TA'd W/ Tubing and Packer in hole.

Size: 7 7/8"

Packer@3604

OPBTD: 3989'

TD: 4030

Set w/17000# tension

3694' -3697' Queen

3702' -3706' Queen

3727' -3729' Queen

3734' -3738' Queen

3745' -3748' Queen

3754' -3762' Queen

3777' -3804' Queen

3810' -3812' Queen

3862' -3867' Queen

3874' -3879' Queen

3889' -3892' Queen

3913' -3915' Queen

3918' -3920' Queen

3936' -3938' Queen

5 1/2" ,15.5/#,J-55 @4030' ,950 ex

Input by: Traci

Approved by:

Last Update: 06/16/10