

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

SEP 30 2013

HOBBSD

Energy, Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. 30-025-30231
5. Indicate Type of Lease STATE ☐ FEE ☐ BLM ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT
8. Well Number 113
9. OGRID Number 004115
10. Pool name or Wildcat DOLLARHIDE QUEEN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GR = 3108'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ INJECTOR

2. Name of Operator
CHAPARRAL ENERGY, LLC.

3. Address of Operator
701 CEDAR LAKE BLVD. OKC, OK 73114

4. Well Location
Unit Letter C : 330 feet from the NORTH line and 2360 feet from the WEST line
Section 31 Township 24S Range 38E NMPM LEA County NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR = 3108'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: BRADENHEAD TEST ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/17/2013 - FAILED BRADENHEAD TEST.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lindsay Reames TITLE ENGINEERING TECH II DATE 9.30.2013

Type or print name LINDSAY REAMES E-mail address: lindsay.reames@chaparralenergy.com PHONE: 405.426.4549

For State Use Only

APPROVED BY [Signature] TITLE DIST. MGR DATE 9-30-2013

Conditions of Approval (if any)

SEP 30 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	API Number 30025302310000 ✓
Property Name WEST DOLLARIDE GREEN SAND UNIT	Well No. 113 ✓

7. Surface Location

UL - Lot C 34	Section 31	Township 24S	Range 38E	Feet from 330	N/S Line FWL	Feet From 2360	E/W Line FWL	County LEA
-------------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status SHUT-IN	PRODUCING Injector	DATE 9/17/2013
-------------------------------	------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0				450
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:
water coming out of casing Failed test 9/17/13
Mark Whitaker witnessed 9/17/2013; "Notice of Violation" 9/19/2013; JAG 9/30/2013.

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address:	
Date: 9-17-13	Phone: 405-227-4298
Witness:	

KB:

DF:

GL: 3108

Chaparral Energy, L.L.C.

Well: West Dollarhide OSU ,113 , 4087.05
 Operator:
 Location: 330' ENL & 2360' FWL, Lea Co., NM
 Legal: Sec. 31-24S-38E
 County: Lea, NM
 LAT/Long: /

Dir:

Spud Date: 02/13/88
 Drilling Finished: 02/20/88
 Completion Date: 07/14/89
 First Production:

TUBING #1:

Type	#Jts	Size	Wt#/f	Grade	Set@
IBC	110	2 3/8"	4.7	J-55	3494'

HISTORY:

07/01/89 - Acidize Queen perfs 3676'-3741' w/1700 gals HCL NEFE acid, 1 1/2 clay stabilizer & 500# rock salt.

07/03/89 - Perf Upper Queen zone 3587'-3651'. Acidize w/3400 gals 15% NEFE acid & 200# rock salt w/25 ball sealers.

07/14/89 - Intial injection rate 408 BPD @ 1100#.

04/1993 - Acidize Queen 3587'-3741' w/1800 gals 15% HCL in 3 stages, pumping 400 gals gelled 10# brine & 400# rock salt between each stage (total treatment 2000 gals acid, 800 gals gelled brine & 800# rock salt).

08/07/08 - Return well to injection.

Size: 12 1/4

8 5/8" ,24 #,K-55 @398' ,250 ex

Size: 7 7/8"

Packer@3494

SN@3494

OPBTD: 3846'

TD: 3910

AD-1, set w/14 pts tension

3587	-3592	Queen	3
3602	-3605	Queen	3
3611	-3615	Queen	3
3622	-3626	Queen	3
3632	-3638	Queen	3
3649	-3651	Queen	3
3676	-3683	Queen	3
3687	-3694	Queen	3
3700	-3706	Queen	3
3713	-3715	Queen	3
3718	-3721	Queen	3
3738	-3741	Queen	3

5 1/2" ,17 #,J-55 @3910' ,1100sx

Input by: Traci

Approved by:

Last Update: 09/15/10