

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
OIL CONSERVATION DIVISION
SEP 30 2013
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBSD

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-30305
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ INJECTOR		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CHAPARRAL ENERGY, LLC.		6. State Oil & Gas Lease No. B-9311
3. Address of Operator 701 CEDAR LAKE BLVD. OKC, OK 73114		7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT
4. Well Location Unit Letter M : 700 feet from the SOUTH line and 55050 feet from the WEST line Section 32 Township 24S Range 38E NMPM LEA County NM		8. Well Number 148
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL = 3135'		9. OGRID Number 004115
		10. Pool name or Wildcat DOLLARHIDE QUEEN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: **BRADENHEAD TEST** ☒

13. Describe proposed or completed operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/17/2013 - WELL FAILED BRADENHEAD TEST.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Lindsay Reames

TITLE **ENGINEERING TECH II**

DATE **9.30.2013**

Type or print name

LINDSAY REAMES

E-mail address: **lindsay.reames@chaparralenergy.com**

PHONE: **405.426.4549**

For State Use Only

APPROVED BY:

[Signature]

TITLE

[Signature]

DATE

9-30-2013

Conditions of Approval (if any):

SEP 30 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	API Number 30025303050000
Property Name West DOWARIDE Queen SAND UNIT	Well No. 148

7. Surface Location

UL - Lot M 37	Section 32	Township 24S	Range 38E	Feet from 700	N/S Line FSL	Feet From 550	E/W Line FWL	County LEA
-------------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status SHUT-IN	PRODUCING	DATE 9/17/2013
-------------------------------	------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			550	920
Flow Characteristics:					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tubing and Casing Com. Failed Test. 9-17-13

Chark Whitaker
Witnessed 9/17/2013;
Notice of Violation 9/18/2013;
WAS
9/30/2013.

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address:	
Date: 9-17-13	Phone: 405-227-4291
Witness:	

KB:

DF:

GL: 3135

Chaparral Energy, L.L.C.

Well: West Dollarhide: QSU , 148 , 4087.08

Operator: CELLC

Location: 700' FSL & 550' FWL, Lea Co., NM

Legal: Sec. 32-24S-38E

County: Lea, NM

LAT/Long: /

Size: 12 1/4

8 5/8" , 24 #, J @412' , 250 sx

Dir:

Spud Date: 07/18/89

Drilling Finished: 07/22/89

Completion Date: 08/15/89

First Production:

TUBING #1:

Type	#Jts	Size	Wt#/f	Grade	Set@
8rd EUE IPC 110	2	3 3/8"	4.7		3460'

HISTORY:

08/07/89 - Perf'd Lower Queen zone 3640'-42', 3647'-49', 3657'-59', 3673'-82', 3692'-97', 3712'-15', 3725'-27', 3 SPF, 4" guns, 69 holes. Acidized w/2000 gals 15% HCL NEFE acid, blocking w/1.3 SG ball sealers (8 balls/2.2 gals).

08/08/89 - Perf'd Upper Queen zone 3553'-58', 3568'-81', 3592'-3602', 3608'-18', 3623'-29'. Acidized w/3000 gals 15% HCL NEFE inhibited acid w/clay stabilizer, blocking w/1.3 SG ball sealers (10 balls/4.5 bbls).

08/15/89 - Started injecting w/260 BPD @ 1250#.

06/1997 - Well TA'd.

07/21/08 - Set IPC pkr & tbg, returned to injection.

07/25/08 - Pressured up to 1500#, would not take any fluid. Pressure did not bleed off until it was manually bled off.

Size: 7 7/8"

Packer@3460'
SS 1.78SN@3460'

OPBTD: 3820'

TD: 3860'

PC AD-1 pkr

3553	-3558	Queen	3
3568	-3581	Queen	3
3592	-3602	Queen	3
3608	-3618	Queen	3
3623	-3629	Queen	3
3640	-3642	Queen	3
3647	-3649	Queen	3
3657	-3659	Queen	3
3673	-3682	Queen	3
3692	-3697	Queen	3
3712	-3715	Queen	3
3725	-3727	Queen	3

5 1/2" , 15.5 #, J @3860" , 1100sx

Input by: Traci

Approved by:

Last Update: 09/10/12