Submit One Copy To Appropriate District Office	State of New Me		Form C-103	
District I 1625 N. French Dr., Hobbs NAM-88240	Energy, Minerals and Natu		WELL API NO.	
District II	OIL CONSERVATION	DIVISION	30-025-05359 5. Indicate Type of Lease	\dashv
811 S. First St., Artesia, NM 88210 District III SEP 2 6 2013 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE 🛛 FEE 🗌	
District IV 1220 S. St. Francis Dr., Santa Fe, NMEIVED 87505	Santa Fe, NM 87	/303	6. State Oil & Gas Lease No.	
	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Lovington San Andres Unit		
1. Type of Well: Oil Well Gas Well Other: Water Injection		8. Well Number: 21 °		
2. Name of Operator Chevron Midcontinent, L.P.			9. OGRID Number 241333	
3. Address of Operator 15 Smith Road Midland, TX 79705		1	10. Pool name or Wildcat Lovington; Grayburg San Andres	
4. Well Location	**************************************			\dashv
1	ne South line and 2310 feet from			
	Range: 37-E NMPM:			
1	 Elevation (Show whether DR, 319' DF 	RKB, RT, GR, etc.)		
12. Check Appropriate Box to In-	dicate Nature of Notice, R	eport or Other Da	ıta	
NOTICE OF INTE	NTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON 🔀 REMEDIAL WOR		☐ ALTERING CASING ☐	ı	
	HANGE PLANS ULTIPLE COMPL	COMMENCE DRIL CASING/CEMENT		
_	OETH LE COMI E	CASING/CLIVILINI	, ,	
OTHER:		☑ Location is rea	ady for OCD inspection after P&A	_
All pits have been remediated in co Rat hole and cellar have been filled	and leveled. Cathodic protection	on holes have been p	roperly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPER			N HAS BEEN WELDED OR	
	arly as possible to original grou	nd contour and has b	een cleared of all junk, trash, flow lines and	!
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials h	ave been removed. Portable ba	ses have been remov	ed. (Poured onsite concrete bases do not have	ve.
to be removed.)		*	ca. (. carea oriste concrete bases do not ha	
All other environmental concerns he Pipelines and flow lines have been a			All fluids have been removed from non	
retrieved flow lines and pipelines.				
		cal service poles and	lines have been removed from lease and we	:ll
location, except for utility's distribution	infrastructure.			
When all work has been completed, retu	n this form to the appropriate I	District office to sched	dule an inspection.	
SIGNATURE 1344 /	TITLE: CI	nevron Construction	Rep DATE 926-13	
TYPE OR PRINT NAME: Bill Beck	E-MAIL: <u>WB</u>	DS@chevron.com	PHONE: 575-390-1412	
For State Use-Only	A	٨٢	011 1 1-11	_
APPROVED BY:	NOWN_TITLE	ampliance	- Effect DATE 10/1/201	ろ
Conditions of Approval (if any)			0013	ሐ
		OCT	0 2 2013	حمال
			MGB	

MGB