

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 08 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHAPARRAL ENERGY LLC	API Number 3002512270000
Property Name WEST DOLLARIDE GUNN SAND UNIT	Well No. 21

7. Surface Location

UL - Lot M	Section 30	Township 24S	Range 38E	Feet from 330	N/S Line FSL	Feet From 990	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN SHUT IN	PRODUCING LAST	DATE 9/12/13
-------------------------	---------------------------	--------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			0	600
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

PSA 3560' - TPA - 3666.
BAD 10/10/2013.
(106' over)

No Defectures Reported
in 10 months.
BAD 10/10/2013

Letter of Violation 10/10/2013 BAD

ELG/OCD 10-8-2013

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address:	
Date: 9-17-13	Phone: 405-227-4298
Witness:	

OCT 10 2013

KB: 3141

DF: 3140

GL: 3131

Size: 13 3/8

9 5/8" ,36 #,J-55 @312' ,300 sx

TOC@ 720'

Size: 8 3/4"

Packer@3560

Size: 6 1/8"

OPBTD: 3915'

TD: 3950

2 3/8" x 4 1/2" PC AD-1 tension pkr

3666	-3672	Queen	3
3680	-3683	Queen	3
3688	-3694	Queen	3
3700	-3706	Queen	3
3710	-3718	Queen	3
3720	-3723	Queen	3
3726	-3729	Queen	3
3764	-3766	Queen	
3770	-3773	Queen	

7" ,23 #,J-55 @3671' ,880 sx

3776	-3779	Queen
3798	-3802	Queen
3804	-3808	Queen
3824	-3827	Queen

4 1/2" ,10.5 #,J-55 @3950' ,460 sx

Chaparral Energy, L.L.C.

Well: West Dollarhide QSU ,#21 ,4087.01

Operator: CELLC

Location: 330' FNL & 990' FWL, Lea Co., NM

Legal: Sec. 30-24S-38E

County: Lea, NM

LAT/Long: /

Dir:

Spud Date: 11/13/53

Drilling Finished: 12/07/53

Completion Date: 12/09/53

First Production: 12/10/53

TUBING #1:

Type	#Jts	Size	Wt#/f	Grade	Set@
8rd	112	2 3/8"			3560'

HISTORY:

Drlg report show 7" TOC @ 1720', other records in well file shows 720' by temp svy.

11-5-92MIRU PU. Unset AD 1 packer. Tag 251' fill. POH with tubing and packer. RIH and bail fill to TD. POH with bailer and test. RIH with tubing and packer to 5000#. Set and test packer/casing to 380# for 15 min. Tested okay. RD&MO.

2-17-94MIRU PU, NDWH, NUBOP, POOH with packer 2-3/8" tubing. RIH with exchange Baker AD 1 packer and 2-3/8" tubing, test to 5000# and replace 1 tubing collar, CH with packer fluid and set packer at 3533'. NDBOP, NUWH. Press casing to 300# - 15 min - held on RDPU

Input by: Traci

Approved by:

Last Update: 04/22/10