

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

OCT 25 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Merit Energy	API Number 30025285120000
Property Name State A-A/c 1	Well No. 117

7. Surface Location

UL - Lot K	Section 3	Township 23 S	Range 36 E	Foot from 1395	N/S Line S	Foot From 1345	E/W Line W	County Lea
----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN Yes	PRODUCING No	DATE 6-3-13
-------------	-----------------------	------------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf Casing	(B) Interm Casing(1)	(C) Interm Casing(2)	(D) Prod Csg	(E) Tubing
Pressure	0	—	—	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

The well had zero pressure on csg. & Surface. Before test. Pressured up on csg. w/ pump truck to 560psi. ran Chart recorder for 33 min. Ending pressure was 560psi.

Signature: [Signature]	ECG/OCD 10-28-2013
Printed name: CHRIS FLORES	OIL CONSERVATION DIVISION
Title: FOREMAN	Entered into RBDMS
E-mail Address: CHRIS.FLORES@MERITENERGY.COM	Re-test
Date: 6-3-13	Phone: 575 420 5506
Witness: [Signature]	

OCT 29 2013