

HOBBS OCD

OCT 25 2013

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Merit Energy	AP# Number 30025285130000
Property Name State A-A/L	Well No. 118

7. Surface Location

UL - Lot 0	Section 3	Township 23-S	Range 36-E	Feet from 1295	N/S Line S	Feet From 2615	E/W Line E	County Lea
----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN Yes	PRODUCING No	DATE 6-6-13
-------------	-----------------------	------------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf Casing	(B) Interm Casing (1)	(C) Interm Casing (2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: The well had a puff on the casing, surface had zero pressure on it before test. We pressured up on casing to 520 psi. w/ Pump truck. Tested w/ chart recorder for 35 min. ending press. was 520 psi.

Signature: 	FLG/OCD 10-28-2013
Printed name: CHRIS FLORES	OIL CONSERVATION DIVISION
Title: FOUR MAN	Entered into RBDMS
E-mail Address: CHRIS.FLORES@MERITENERGY.COM	Re-test
Date: 10-9-13	
Phone: 575 426 5300	
Witness:	

OCT 29 2013