

HOBBS OCD

OCT 25 2013

RECEIVED

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Merit Energy		API Number 30025285160000	
Property Name State A-A/L 1		Well No. 121	

7. Surface Location

UL - Lot 0	Section 3	Township 23-S	Range 36 E	Feet from 85	N/S Line S	Feet From 1460	E/W Line E	County LEA
----------------------	---------------------	-------------------------	----------------------	------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN YES	PRODUCING NO	DATE 6-3-13
-------------	-----------------------	------------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf Casing	(B) Interm Casing (1)	(C) Interm Casing (2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	0	2#
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Casing and Surface were Neutral before test.
Pressure up on csg. to 540# with pump truck tested
with chart recorder for 33 min. Ending pressure 540psi.

Signature: CMH	EG/OCD 10-28-2013
Printed name: CHARIS FLORES	OIL CONSERVATION DIVISION
Title: FOREMAN	Entered into RBDMS
E-mail Address: CHARIS.FLORES@MERITENERGY.COM	Re-test
Date: 6-3-13	Phone: 575 420 5506
Witness:	

OCT 29 2013