

HOBBS OCD

OCT 31 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-23031
Property Name Quail Queen Unit	Well No. 8

Surface Location

UL - Lot K	Section 11	Township 19S	Range 34E	Feet from 2080	N. S. L. FSL	Feet from 1980	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Injector	DATE 10/2/2013
-------------------------	---------	------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0			400	800
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / N	Y / N	☒ Y / N *	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	Y / N	Y / N	Y / ☒ N *	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	☒ Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	☒ FRESH	SALTY	SULFUR	BLACK
-------	--	-------	--------	-------

Remarks:

D. Production Casing - Took 3 minutes to bleed down.
- 1 cup of fresh water was present *

Signature: [Signature]	ELG/OCD 10-30-2013
Printed name: Justin Hobbs	OIL CONSERVATION DIVISION
Title: PSSS	Entered into RBDMS
E-mail Address: JHobbs@chevron.com	Re-test
Date: 10/2/2013	
Phone: 575-631-4228	
Witness:	

NOV 04 2013