

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 31 2013

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	AP# 30-025-24916
Property Name Antelope Ridge Sub Unit	Well No. 5

UL - Lot L	Section 33	Township 23S	Range 34E	Feet from 2310	Section FSL	Feet from 990	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Injector (sub)	DATE 10/1/2013
-------------------------	---------	------------------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0			0	480
Flow Characteristics					
Puff	Y / 0	Y / N	Y / N	Y / 0	
Steady Flow	Y / 0	Y / N	Y / N	Y / 0	
Surges	Y / 0	Y / N	Y / N	Y / 0	
Down to nothing	0 / N	Y / N	Y / N	0 / N	
Gas or Oil	Y / 0	Y / N	Y / N	Y / 0	
Water	Y / 0	Y / N	Y / N	Y / 0	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks:

ELG/ocd 10-30-2013

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: Jhobbs@chevron.com	
Date: 10/1/2013	Phone: 575-631-4228
Witness:	

NOV 04 2013