

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 31 2013

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	Chevron USA INC.	API Number	30-025-25493
Property Name	Quail Queen Unit	Well No.	14

Surface Location									
Utl. - Lot	Section	Township	Range		Feet from	Section	Feet from	E/W Line	County
G	14	19S	34E		1980	FNL	1680	FEL	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
S	Injector		10/2/2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1-Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0			34	500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

D. - Production Casing
- It took 1 minute to bleed down to 0 PSI.
1/2 cup water came out. (* Did Fluid/Water Bleed Down?
Ambiguous Response)
NOI TO PTA Approved 4/8/2013.
NO Injection as of 10/1/2012 & 11/1/13.
Injection line repair - Temporary
Letter of Violation
10/1/13
10/30/2013

Signature:	<i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name:	Dustin Hobbs	Entered into RBDMS
Title:	PSSS	Re-test
E-mail Address:	Jhobbs@Chevron.com	
Date:	10/2/2013	Phone: 575-631-4228
Witness:		

NOV 04 2013