

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 31 2013

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-33883
Property Name SV Big Bertha	Well No. 1

Surface Location

UL - Lot F	Section 11	Township 16S	Range 36E	Feet from 2081	N/S Lot FUL	Feet from 1870	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Injection Well	DATE 10/17/2013
-------------------------	---------	------------------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	5.9	1.5		22	-3
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☒ N	
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☒ Y ☐ N	☐ Y ☒ N *	
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Down to nothing	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N *	
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

D. - Production Casing - It took 2 minutes to bleed the casing down to 0 psi. *

Signature: 	ELG/OCD 10-30-2013 OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: jhobbs@chevron.com	
Date: 10/17/2013	Phone: 575-631-4228
Witness:	

NOV 04 2013