

OCT 31 2013

RECEIVED

District 1
1625 N. French Dr., Hobbs, NM 88249
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA INC.					API Number 30-025-35985				
Property Name Trinity Burrus Abo Unit					Well No. 26				
Surface Location									
UL - Lot B	Section 27	Township 12S	Range 38E		Feet from: 330	Feet from: FNL	Feet from: 2000	E/W Line FEL	County Lea

Well Status Injector		SHUT-IN		DATE 10/8/2013	
Well Status A					

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0			300	900
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
--------------	--------------	--------------	---------------	--------------

Remarks:

D- Production Casing - It took 1 minute to bleed down to 0 psi.
- About 1 gallon of water present. *

ELG/ocd 10-30-2013

Signature: J. Hobbs		OIL CONSERVATION DIVISION	
Printed name: Justin Hobbs		Entered into RBDMS	
Title: PSSS		Re-test	
E-mail Address: jhobbs@chevron.com			
Date: 10/8/2013	Phone: 575-631-4228		
Witness:			

NOV 04 2013