

HOBBS OCD

HOBBS OCD

OCT 31 2013

OCT 31 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

RECEIVED

BRADENHEAD TEST REPORT

Operator Name

Chevron USA Inc.

API Number

30-025-36038

Property Name

Trinity Burrus Abo Unit

Well No.

11

Surface Location

UL - Lot

Section

Township

Range

Feet from

Section

Feet from

E/W Line

County

16

22

12S

38E

1650

FSL

2310

FWL

Lea

Well Status

Well Status

A

SHUT-IN

PRODUCING

Injector

DATE

10/8/2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0	0		500	800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N *	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N *	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

D. - Production Casing - It took 1 minute to bleed down into truck.
- Small amount of water and skim of oil.

Violation Letter
11/1/13 JAD

(PT 11/2010.)

ELG/OCD 10-30-2013

Signature: <i>J Hobbs</i>	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: <i>Jhobbs@chevron.com</i>	
Date: 10/8/2013	Phone: 575-631-4228
Witness:	

NOV 04 2013