

HOBBS OCD

NOV 07 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Name Chevron USA Inc	API Number 3002512347
Operator Pollarhide (WDDU)	Well No. WDDA 73

Surface Location

UL - Lot N	Section 33	Township 24S	Range 38E	Feet from 560	Section S	Feet from 780	Township E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	---------------------	-------------------------	----------------------	----------------------

Well Status

Well Status A	SHUT-IN Active	PRODUCING Inj	DATE 9/12/13
-------------------------	--------------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0	0	0	1300	1300
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
--------------	--------------	--------------	---------------	--------------

Remarks:

Signature 	OIL CONSERVATION DIVISION
Printed name Luke Robertson	Entered into RBDMS
Title Field Specialist	Re-test
E-mail Address LRK@chevron.com	
Date 9/13/13	
Phone 432 266 2806	
Witness	

NOV 13 2013